



## Freediving Manual

www.dive-xtras.com  
4433 Russell Rd, STE 106  
Mukilteo  
WA 98275 USA  
Tel: 425 296 6570  
Fax: 425 493 9320

Parts included in with your new Saddle:

- 2 x Face Plates
- 1 x Saddle
- 4 x Leg Bracers
- 8 x bolt and washer set
- 1 x thread rod with 2 washers and nuts
- 2 x Cam Straps

Tools you will need:

- 1 x 7/16" wrench



Attach the two Face Plates to the saddle. Insert threaded rod through the holes in the Face Plates. Place washers on ends and install nuts. Do not over-tighten.



Install the leg bracers using bolt set. The front side should be slightly lower than the back side for proper fit. Adjust to preference.





## Freediving Manual

[www.dive-xtras.com](http://www.dive-xtras.com)  
4433 Russell Rd, STE 106  
Mukilteo  
WA 98275 USA  
Tel: 425 296 6570  
Fax: 425 493 9320

Thread Cam Strap through face plates. Leave loose for now. Will tighten on the scooter.



The Cam Strap should fit in the pre made grooves for a streamline appearance.



Tighten the Cam Straps once on the Scooter. Adjust as needed.





## Freediving Manual

[www.dive-xtras.com](http://www.dive-xtras.com)  
4433 Russell Rd, STE 106  
Mukilteo  
WA 98275 USA  
Tel: 425 296 6570  
Fax: 425 493 9320

Plug freediving electronics into 3 point connector for regular trigger operation.



Plug freediving electronics into 2 point connector for freediving remote operation.

